

PANOLA
R 61
10-18-73

MISSISSIPPI
BOARD OF WATER COMMISSIONERS
416 North State Street
Jackson, Mississippi 39201

CODED

WATER WELL DRILLERS LOG

10-18 1973 LiPe Well Co. Panola
date well completed firm name county well located

LANDOWNER:
Rubber plant
Batesville Miss,
(mailing address)

description of formations encountered	from	to
<u>TOP soil</u>	<u>0</u>	<u>20</u>
<u>sand</u>	<u>20</u>	<u>40</u>
<u>ll</u>	<u>40</u>	<u>60</u>
<u>ll</u>	<u>60</u>	<u>80</u>
<u>ll</u>	<u>80</u>	<u>110</u>

WELL LOCATION:
sec. 9 T. 9 N R. 8 7W
1/4 miles East of Batesville
(distance) (direction) (nearest town)

WELL PURPOSE:
(home, irrigation, municipal, Industrial)

- WELL COMPLETION DATA:
- (1) diameter (inches) 4
 - (2) total depth (feet) 110
 - (3) static water level (feet) 28 below above top of ground.
 - (4) casing PVC, 100
(material) (depth)
4 If telescope see back.
(size)
 - (5) screen 10, 100
(length) (depth to top)
4 PVC
(size) (material)
 - (6) pump 3 50
(HP) (yield gpm)
elec.
(type power)
 - (7) electric log no
(yes or no)
no
(organization running log)
 - (8) how well bottom plugged PVC
cap

CODED

DRILLERS REMARKS: _____

10/17/73 5 1073

