

PANOLA 4  
U 58  
14399

MISSISSIPPI  
BOARD OF WATER COMMISSIONERS  
416 North State Street  
Jackson, Mississippi 39201

Coded / Entered

WATER WELL DRILLERS LOG

12-11e 1991 Lipe Well Supply Panola  
date well completed firm name county well located

LANDOWNER: Independence  
Water Associates  
Curtland Ms  
(mailing address)  
WELL LOCATION:  
sec. 1 T 20 N R 13 E  
3 miles west of Curtland  
(distance) (direction) (nearest town)

description of formations encountered	from	to
top soil and red sand	0	20
red sand	20	40
red sand with streak of gravel with sand	40	60
little sand and gravel	60	80
clay	80	150
sand	100	160
sand and clay	160	250
sand	250	240

WELL PURPOSE: u  
(home, irrigation, municipal, industrial)

WELL COMPLETION DATA:  
(1) diameter (inches) 8"  
(2) total depth (feet) 240'  
(3) static water level (feet) 140' below top of ground.  
(4) casing Steel, 250' (material) (depth)  
8" (size) If telescope see back.  
(5) screen 30', 210' (length) (depth to top)  
6", Stainless Steel (size) (material)  
(6) pump 10 HP, 150 (yield gpm)  
elec. (type power)  
(7) electric log (yes or no) no  
(organization running log)  
(8) how well bottom plugged cap

RECEIVED  
JAN 08 1992

Dept. of Environmental Quality  
Bureau of Land & Water Resources

DRILLERS REMARKS:  
good wells

If well telescopes please sketch and show depths.

**GROUND LEVEL**


**SECTION** \_\_\_\_\_

Please indicate well location X.

**ADDITIONAL INFORMATION**

If more than one screen,  
show locations of each on sketch.