

QU-47
3-24-63

WATER WELL DRILLERS LOG

CODED
PEARL
County RIVER

Date: 3/24, 1963, Driller: POUPART
868-35
(Name)

(1) Owner of Land: Louis MITCHEL
(Name)
FLAT-TOP
(Address)
31 5' 18

(2) Location: 1/4, 1/4, Sec. 31 T. 5 R. 12
5 miles EAST, of PICAYUNE
(distance) (direction) (Nearest Town)

(3) Topography: Flat
(Hilly) (Flat) (Level)

(4) Purpose of Well: DOMESTIC
(Domestic Irrigation
Municipal, Industrial, Other)

Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
SOIL red CLAY.	20	
SAND & GRAVEL	20	40
Blw CLAY.	200	240
SAND	40	280
Blw CLAY	90	360
SAND	20	380
Blw Clay.	130	510
SAND & (Peanut Shell)	190	705

Information upon completion of well:

(1) Diameter 2 inches.

(2) Total Depth 705 feet.

(3) Water Level FLOW feet below top of ground.

(4) Cased to _____, Size _____

(5) Screen: Size 10, Length 30'


(6) Were any formations sealed against pollution?
_____ yes, _____ no.

CODED

If YES depth of formation _____

Why _____

Drillers Remarks: _____



(Use Back Side)

Well No.

1912

1. The first part of the report deals with the general situation of the country and the progress of the work during the year. It is divided into two main sections, the first of which deals with the general situation and the second with the progress of the work.

2. The general situation of the country is described in the first section. It is found that the country is generally prosperous and that the progress of the work is satisfactory. The second section deals with the progress of the work during the year. It is found that the work has been carried out in accordance with the plan and that the results are satisfactory.

3. The second part of the report deals with the details of the work. It is divided into three main sections, the first of which deals with the general situation of the work, the second with the progress of the work, and the third with the results of the work.

4. The general situation of the work is described in the first section. It is found that the work is generally well advanced and that the progress is satisfactory. The second section deals with the progress of the work during the year. It is found that the work has been carried out in accordance with the plan and that the results are satisfactory.

5. The results of the work are described in the third section. It is found that the work has been carried out in accordance with the plan and that the results are satisfactory. The work has been carried out in accordance with the plan and the results are satisfactory.