

MISSISSIPPI DEPARTMENT OF ENVIRONMENT QUALITY

Office of Land and Water Resources

P. O. Box 2309

Jackson, MS 39225

Water Well Plugging/Decommissioning Form

OLWR-DF-1 (4/08)

COUNTY WELL LOCATED: Pike		WELL NUMBER: 570010-1	
PERMIT NUMBER: MS-GW-02224		DATE WELL PLUGGED: 07/18/2012	
NAME OF FIRM PLUGGED WELL: Mid-South Water and Machine Works, LLC TELEPHONE NUMBER: (662) 843-4076			
NAME AND ADDRESS OF CURRENT LANDOWNER: Town of Osyka 310 Wall Street West Osyka, MS 39657			
WELL LOCATION	SECTION	TOWNSHIP	RANGE
WELL LOCATION LATITUDE N31° 0' 14.303"	LONGITUDE W90° 28' 6.7"	METHOD (CIRCLE ONE) (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) GPS - HAND HELD OR SURVEY GRADE	
DISTANCE 280' DIRECTION East NEAREST TOWN OTHER LANDMARK: E. Railroad Ave on North side of Pike St.			
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Municipal			
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL: Unknown			
NAME OF LANDOWNER WHEN WELL WAS DRILLED: Town of Osyka			

WELL DATA			
WELL DEPTH: 170'	HOLE DEPTH:		
CASING DIAMETER (IN) 10"	CASING LENGTH (FT.) 150'	TYPE OF CASING Steel	
DEPTH TO STATIC WATER LEVEL: 24'	DATE WELL COMPLETED: 1958		
WHY IS THE WELL BEING ABANDONED? Does not produce water			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

No pump in well.

Ran 2" pipe run to 140'.

Pumped 5 yd³ of cement into well.

Got cement returns at ground surface.

Removed concrete foundation.

Cut casing off 3' below grade.

Backfilled with dirt and smoothed well site.

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS

<u>Clayton Miller</u> PRINT NAME	<u>0-703</u> MS LICENSE NUMBER
<u><i>Clayton Miller</i></u> SIGNATURE	<u>07-28-2012</u> DATE