

LEE

MISSISSIPPI BOARD OF WATER COMMISSIONERS

G D 21  
2-13-62

PONT TO TOC

GODWIN WATER WELL DRILLERS LOG

HERNDON WELL & SUPPLY CO.

Date: 2-13, 1962, Driller: \_\_\_\_\_ P. O. BOX 42 County: Lee

SHANNON, MISSISSIPPI

(1) Owner of Land:	Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
Archie Pott (Name) Rt 1 Turgala Miss (Address)	Surface sand & clay		0
(2) Location: $\frac{1}{4}$ , NE $\frac{1}{4}$ , Sec. <u>24</u> T. <u>9 S</u> R. <u>2 E</u> 6 miles West of Turgala (distance) (direction) (Nearest Town)	Blue Rock Sand		23 175
(3) Topography: Hilly (Hilly) (Flat) (Level)	Hard Rock		120
(4) Purpose of Well: Domestic (Domestic Irrigation Municipal, Industrial, Other)	Sand & rock		192
Information upon completion of well:	Gambo		400
(1) Diameter: <u>4</u> inches.	Sand		560
(2) Total Depth: <u>720</u> feet.	Bottom		700
(3) Water Level: <u>178</u> feet below top of ground. <u>40' 8"</u>	1.5 inch		
(4) Cased to: <u>83'</u> Size: <u>4"</u> <u>210'</u> <u>2 1/2"</u>	(Use-Back Side)		
(5) Screen: Size: <u>2"</u> , Length: <u>20'</u>	MISS. BOARD OF WATER COMMISSIONERS FEB 16 1962 RECEIVED		
(6) Were any formations sealed against pollution? <input checked="" type="checkbox"/> yes, _____ no.	Well No.		
If YES depth of formation: <u>370'</u>			
Why: <u>Surface &amp; sand</u>			
Drillers Remarks: <u>Backers up at house</u>			
<u>10.3 ELEV 402</u>			

