RANKIN
L 3024
6-17-64

MISSISSIPPI BOARD OF WATER COMMISSIONERS

WATER WELL DRILLERS LOG

CODED 8/13

Date: 6-17-, 19 64, Driller: Layne-Central Co. (Name) County: Rankin

(1) Owner of Land: Town of Brandon (Name)

Brandon, Mississippi (Address)

(2) Location: ___ ¼, ___ ¼, Sec. 16 T 5 R 3,

___ miles (distance) ___ (direction), of ___ (Nearest Town),

(3) Topography: ___ (Hilly) (Flat) (Level)

(4) Purpose of Well: municipal (Domestic Irrigation Municipal, Industrial, Other)

Information upon completion of well:

(1) Diameter 16 inches.

(2) Total Depth 1282 feet.

(3) Water Level 283 feet below top of ground.

(4) Cased to 1212', Size 16",

(5) Screen: Size 10", Length 60'.

(6) Were any formations sealed against pollution?

x yes, ___ no.

If YES depth of formation 1212',

Why required

Drillers Remarks:

Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thickness Feet	Depth Feet
sandy clay	3	3
loose sand-sks. clay	17	20
loose sand	60	80
clay	20	100
lime rock-soft stks	26	126
sand-clay stks	49	175
sand-clay & lignite	15	190
clay	133	323
rock	1	324
clay	298	622
rock	2	624
clay-stks lime	40	664
sandy shale	85	749
clay	16	765
hard sandy shale	25	790
sandy clay	30	820
sand	70	890
fine sandy shale	40	930
sandy shale	77	1007
gummy shale	78	1085
rock	1	1086
shale, hard	9	1095
rock	2	1097
shale	73	1170
sandy shale	55	1225
sand-bks. clay	68	1293
shale	5	1298

RECEIVED JUN 1 1964 MISS. BOARD OF WATER COMMISSIONERS

(Use Back Side)

Well No.

Mail this copy to Board of Water Commissioners 429 Miss. St. Jackson, Miss.

(7)