

RANKIN MISSISSIPPI BOARD OF WATER COMMISSIONERS

P 64

3-21-66

WATER WELL DRILLERS LOG

**CODED**

Date: 3/21, 19 66, Driller: East Drilling County Rankin  
(Name)

(1) Owner of Land: Lee A. Johnson  
(Name)  
R. F. Brandon, Mrs.  
(Address)

(2) Location: 1/4, 1/4, Sec. 25 T 4R 2  
8 miles Southwest of Brandon  
(distance) (direction) (Nearest Town)

(3) Topography: \_\_\_\_\_  
(Hilly) (Flat) (Level)

(4) Purpose of Well: Home  
(Domestic Irrigation  
Municipal, Industrial, Other)

Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
<u>Clay</u>		<u>17</u>
<u>Sand</u>		<u>25</u>
<u>Hard Shale + Silts Rock</u>		<u>30</u>
<u>Black Rock</u>		<u>100</u>
<u>Shale, Silts Rock + Shale</u>		<u>148</u>
<u>Rock</u>		<u>150</u>
<u>Rock + Silts fine Clay</u>		<u>184</u>
<u>Home Sand + Shale</u>		<u>210</u>
<u>Silt + Silts Sand</u>		<u>215</u>
<u>Silt Mucky Clay</u>		<u>287</u>
<u>Shale + Silts</u>		<u>297</u>
<u>Silt + Silts + Silts Rock</u>		<u>293</u>
<u>Shale + Silts + Silts</u>		<u>718</u>
<u>Silt + Silts + Silts + Silts</u>		<u>739</u>
<u>Silt + Silts + Silts</u>		<u>765</u>
<u>Silt + Silts + Silts</u>		<u>805</u>
<u>Silt + Silts + Silts</u>		<u>858</u>
<u>Silt + Silts + Silts</u>		<u>875</u>
<u>Silt + Silts + Silts</u>		<u>913</u>
<u>Silt + Silts + Silts</u>		<u>915</u>
<u>Silt + Silts + Silts</u>		<u>921</u>
<u>Silt + Silts + Silts</u>		<u>926</u>
<u>Silt + Silts + Silts</u>		<u>941</u>
<u>Silt + Silts + Silts</u>		<u>973</u>
<u>Silt + Silts + Silts</u>		<u>1006</u>

Information upon completion of well:

(1) Diameter 2 inches.

(2) Total Depth 1006 feet.

(3) Water Level 150 feet below top of ground.

(4) Cased to 986, Size \_\_\_\_\_

(5) Screen: Size 2", Length 20ft.


(6) Were any formations sealed against pollution?  
\_\_\_\_\_ yes,  no.

If YES depth of formation \_\_\_\_\_

Why \_\_\_\_\_

Drillers Remarks: \_\_\_\_\_

**CODED**



(Use Back Side)

Well No.

