

03/02/1996 16:02 6014281435

A-1 DRILLING SERVICE

PAGE 14

### State Well Report

#### Part 1

Mississippi Department of Environmental Quality  
 Office of Land and Water Resources  
 P.O. Box 10631  
 Jackson, MS 39289-0631  
 (601)961-5210  
 (601)354-6938 (fax)

#### For Office Use Only:

Aquifer: \_\_\_\_\_  
 Well #: C-377  
 L.S. Elevation: \_\_\_\_\_  
 E-log #: \_\_\_\_\_

County: Smith  
 Permit #: \_\_\_\_\_  
 Driller: A-1 Drilling Serv.  
 Date drilling completed: 10-20-05

State Law requires that this report be prepared by the driller in detail and filed with the Department within 30 days of completion of drilling of the well.

Well Owner Information <u>WELL # 2005-2</u>		Well Location	
Owner Name: <u>BATTE LUMBER Co.</u>	Latitude: _____ " Longitude: _____ "	Method of Lat/Long (circle one): Conventional Survey.	
Mailing Address: <u>PO Box 707</u>	USGS quad, Hand-held GPS, Survey-grade GPS		
<u>Forest</u> <u>Miss.</u> <u>39074</u>	<u>NW 1/4 NE 1/4 Sec 29 Twn 4 N Rng 8 E</u>		
City State Zip Code	Distance <u>1 1/2</u> Miles	Direction <u>S</u>	Nearest Town <u>Lorena</u>
Telephone No. <u>(601) 536-2096</u>			

#### Well Data

Purpose of Well (circle one) Home  Industrial  Public Supply  Irrigation  Fish Culture  Other: Log Sprinkling

Date well drilling started: 10-17-05 Date well drilling completed: 10-20-05

If flowing, method of flow regulation: Valve \_\_\_\_\_ Other (describe) \_\_\_\_\_

Static Water Level: 75' feet above or  below (circle one) land surface Date measured: 10-18-05

Method of Measurement (circle one) steel tape  electric tape  air line other: \_\_\_\_\_

Hole depth: 100 Well depth: 108 Well grouted to a depth of 13 feet

Type of grout (circle one):  Cement  Bentonite  Mix

Casing length: 80 feet Casing diameter: 4 inches Type of casing: PVC

Screen length: 20 feet Screen diameter: 4 inches Type of screen: slotted PVC

Screen slot size: .006 inches Setting depth: From 80 feet to 100 feet

Type of completion (circle all applicable): Gravel packed  Underreamed  Telescoped  Open hole  Natural Development

Other (describe): This well produced insufficient amt of water - abandoned & grouted up

Top of lap pipe or reduction in casing: \_\_\_\_\_ feet. If telescoped or more than one screen, describe on back of page

Logs run (circle all applicable):  No log run  Electric  Gamma Ray  Density  Sonic  Neutron Other: \_\_\_\_\_

Name of organization running log(s): \_\_\_\_\_

I certify that the well was drilled, constructed, and completed in accordance with all applicable requirements of the Mississippi Department of Environmental Quality and/or the Mississippi Department of Health regulations and state laws.

Mike Baughman 587  
 Print Name of Water Well Contractor and License No.

Mike Baughman  
 Signature of Water Well Contractor

03/02/1996 16:02 6014281435


A-1 DRILLING SERVICE

PAGE 15

C-27

If well telescopes please sketch below and show depths.

Ground Level



Description of Formations Encountered	From	To
Red sandy clay	0	9
Tan clay	9	11
Red sandy clay	11	15
Tan clay	15	22
Brown clay	22	29
Sandy streak	29	74
clay break	74	78
Sand	78	100
clay break	100	102

If more than one screen, show location of each on sketch

Sketch the property layout and include the following: 1) the well location; 2) any permanent structures on the property that may aid in locating the well; 3) any roads, power lines, or other items that may aid in locating the property and the well; 4) indicate direction.

Landowner Name: BATTE LUMBER CO WELL # 2005-2

[Signature]  
Signature of Water Well Contractor