MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY

Office of Land and Water Resources

P. O. Box 2309 Jackson, MS 39225

Water Well Plugging/Decommissioning Form OLWR-DF-1 (04/08)

COUNTY WELL LOCATED: Stone	WELL NUMBER: 131 F0036
111	
PERMIT NUMBER: NA	DATE WELL PLUGGED: /0//6//8
NAME OF FIRM PLUGGING WELL: Lynan Well	228-832-3/93
NAME AND ADDRESS OF MS Gulf Coast Connunity College	
51 Main St Verkinston MS, 39573 WELL LOCATION: SECTION: /2 TOWNSHIP: 35 RANGE: 12W	
WELL LOCATION: SECTION: /3 TOWNSHIP: 35 RANGE: /2W	
WELL LOCATION: LATITUDE: LONGITUDE: METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY GRADE 30° 47'03,08N 89°08'43,03 W (3) GPS - HAND HELD OR SURVEY GRADE	
DISTANCE: DIRECTION: NEAREST TOWN: OTHER LANDMARK: Foot 6/1/ Field	
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Irrigation	
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:	
NAME OF LANDOWNER WHEN WELL WAS DRILLED:	
WELL DATA	
WELL DEPTH: 200	HOLE DEPTH: 200
CASING DIAMETER (IN.): 4/1 CASING LENGTH (FT.): 20	O TYPE OF CASING: PW
DEPTH TO STATIC WATER LEVEL: 50 DATE WELL COMPLETED: NA	
WHY IS THE WELL BEING ABANDONED? New Road	
DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.) Tremnie pipewas an and 20 cuff of neat Cenent was pumped to the surface, Casing	
had a hole in it apparently from lightning.	
RECEIVED	
OCT 18 2018	
BYOLWR	
I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.	
Josh Ladrer	0-640
Losh hadrer Alk print NAME	MS LICENSE NUMBER 10/16/18

SIGNATURE

DATE

