

~~OK 21~~ 629

WATER WELL DRILLERS LOG

CODED

12-4-64

Date: 12/4, 1964, Driller: Delta Wells Supply Co. County: Jefferson
(Name)

(1) Owner of Land: Linn Baptist Church
(Name)
Linn, Miss.
(Address) 16 21

(2) Location: 1/4, 1/4, Sec. 10-TORT,
_____ miles _____ of Linn
(distance) (direction) (Nearest Town)

(3) Topography: (Hilly) (Flat) (Level)

(4) Purpose of Well: _____
(Domestic Irrigation
Municipal, Industrial, Other)

Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
<u>Sand clay</u>	<u>165</u>	
<u>" gravel</u>	<u>75</u>	<u>120</u>
<u>Clay</u>	<u>180</u>	<u>300</u>
<u>sand</u>	<u>30</u>	<u>330</u>
<u>Clay</u>	<u>184</u>	<u>514</u>
<u>sand</u>	<u>4</u>	<u>518</u>
<u>Rock</u>	<u>1</u>	<u>519</u>
<u>Clay & shale</u>	<u>198</u>	<u>717</u>
<u>sand</u>	<u>8</u>	<u>720</u>
<u>Clay</u>	<u>2.05</u>	<u>925</u>
<u>Rock</u>	<u>1</u>	<u>926</u>
<u>Clay</u>	<u>16</u>	<u>942</u>
<u>Rock</u>	<u>2</u>	<u>944</u>
<u>Clay</u>	<u>37</u>	<u>981</u>
<u>Rock</u>	<u>4</u>	<u>985</u>
<u>Clay</u>	<u>35</u>	<u>1020</u>
<u>Rock</u>	<u>3</u>	<u>1023</u>
<u>Clay</u>	<u>9</u>	<u>1030</u>
<u>subtle sand</u>	<u>6</u>	<u>1036</u>
<u>Rock</u>	<u>2</u>	<u>1038</u>
<u>Bank dark</u>	<u>49</u>	<u>1087</u>
<u>Rock</u>	<u>2</u>	<u>1089</u>
<u>sand & clay</u>	<u>51</u>	<u>1140</u>
<u>Sand</u>	<u>36</u>	<u>1176</u>

Information upon completion of well:

(1) Diameter 4 1/2 inches.

(2) Total Depth 1176 feet.

(3) Water Level Flow feet below top of ground.

(4) Cased to _____, Size _____


(5) Screen: Size 2, Length 20ft.

(6) Were any formations sealed against pollution?
_____ yes, _____ no.

If YES depth of formation _____

Why _____

Drillers Remarks: _____



(Use Back Side)

Well No.

