

DEQ

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY  
Office of Land and Water Resources  
P. O. Box 2309  
Jackson, MS-39225  
Water Well Plugging/Decommissioning Form  
OLWR-DF-1 (04/08)

no drill log

COUNTY WELL LOCATED: Sunflower	WELL NUMBER: M
PERMIT NUMBER: GW-13686	DATE WELL PLUGGED: 9-23-2019
NAME OF FIRM PLUGGING WELL: Irrigation Equipment Inc.	TELEPHONE NUMBER: 662-887-2555
NAME AND ADDRESS OF CURRENT LANDOWNER: Westchester Mgt. Group (IAI USA Fund II) 1207 Cardinal Circle Indianola MS 38751	662-207-0269
WELL LOCATION: SECTION: 3 TOWNSHIP: 19N RANGE: 5W	
WELL LOCATION: LATITUDE: 33 31 16.0 LONGITUDE: 90 41 53.4	METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) GPS - HAND HELD OR SURVEY GRADE
DISTANCE: DIRECTION: NEAREST TOWN: Indianola	OTHER LANDMARK:
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Irrigation	
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:	
NAME OF LANDOWNER WHEN WELL WAS DRILLED:	

WELL DATA			
WELL DEPTH: 106Ft.	HOLE DEPTH:		
CASING DIAMETER (IN.): 8	CASING LENGTH (FT.):	TYPE OF CASING: PVC	
DEPTH TO STATIC WATER LEVEL: 39Ft.	DATE WELL COMPLETED:		
WHY IS THE WELL BEING ABANDONED? Replaced			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

Removed casing below ground level. Installed 5% chlorine bleach. Installed sand and gravel. Installed 500 pounds of bentonite hole plug.

New Well Drilled: GW-50842

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.

Patrick M Chism  
PRINT NAME

SIGNATURE

0695  
MS LICENSE NUMBER  
10-11-2019  
DATE

RECEIVED  
OCT 14 2019  
BY OLWR



Google Earth



RECEIVED  
OCT 14 2019  
BY OLWR  
RECEIVED  
OCT 14 2019  
BY OLWR