

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
 Office of Land and Water Resources
 P. O. Box 2309
 Jackson, MS 39225
Water Well Plugging/Decommissioning Form
 OLWR-DF-1 (04/08)
 (601)961-5555 (601)961-5228 (fax)

DEQ


no drill log

COUNTY WELL LOCATED: Sunflower		WELL NUMBER: 5
PERMIT NUMBER: GW-07414	DATE WELL PLUGGED: 10-18-2019	
NAME OF FIRM PLUGGING WELL: Irrigation Equipment Inc.	TELEPHONE NUMBER: 662-887-2555	
NAME AND ADDRESS OF CURRENT LANDOWNER: Hancock Farmland Services 1803 Woodfield Drive, Suite B Savoy IL 61874	(Sunflower 82 Farm)	
WELL LOCATION: NW/NW	SECTION: 9	TOWNSHIP: 17N RANGE: 5W
WELL LOCATION: LATITUDE: 33 20 30.3	LONGITUDE: 90 43 33.8	METHOD (Check ONE): <input checked="" type="checkbox"/> USGS QUAD <input type="checkbox"/> CONVENTIONAL SURVEY <input type="checkbox"/> GPS - HAND HELD OR SURVEY GRADE
DISTANCE:	DIRECTION:	NEAREST TOWN: Inverness OTHER LANDMARK:
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.):	Irrigation	
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:		
NAME OF LANDOWNER WHEN WELL WAS DRILLED:		

WELL DATA		
WELL DEPTH: 110Ft.	HOLE DEPTH:	
CASING DIAMETER (IN.): 16"	CASING LENGTH (FT.):	TYPE OF CASING: Steel
DEPTH TO STATIC WATER LEVEL: 30Ft.	DATE WELL COMPLETED:	
WHY IS THE WELL BEING ABANDONED? Replaced		

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.) Removed casing below ground level. Installed 5% chlorine bleach. Installed sand and gravel. Installed bentonite hole plug.
New Well: GW-51022

RECEIVED
NOV 08 2019
BY OLWR

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.	
Patrick M Chism  PRINT NAME	0695 MS LICENSE NUMBER 11-4-2019 DATE
SIGNATURE	DATE



Google Earth

feet
meters



RECEIVED
NOV 08 2019
BY OLWR