

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
Office of Land and Water Resources
 P. O. Box 2309
 Jackson, MS 39225
Water Well Plugging/Decommissioning Form
 OLWR-DF-1 (04/08)
 (601)961-5555 (601)961-5228 (fax)

DEQ

no drill log

COUNTY WELL LOCATED: Sunflower	WELL NUMBER: T
PERMIT NUMBER: GW-14546	DATE WELL PLUGGED: 5-6-2020
NAME OF FIRM PLUGGING WELL: Irrigation Equipment Inc.	TELEPHONE NUMBER: 662-887-2555
NAME AND ADDRESS OF CURRENT LANDOWNER: Lake Dawson Plantation 164 Gene Lester Rd Isola MS 38754	662-207-1192
WELL LOCATION: SE/SE SECTION: 33 TOWNSHIP: 17N RANGE: 4W	
WELL LOCATION: LATITUDE: 33 16 21.6 LONGITUDE: 90 36 32.4	METHOD (Check ONE): <input type="checkbox"/> USGS QUAD <input type="checkbox"/> CONVENTIONAL SURVEY <input checked="" type="checkbox"/> GPS - HAND HELD OR SURVEY GRADE
DISTANCE: DIRECTION: NEAREST TOWN: Isola OTHER LANDMARK:	
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Irrigation	
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:	
NAME OF LANDOWNER WHEN WELL WAS DRILLED:	

WELL DATA		
WELL DEPTH: 119Ft.	HOLE DEPTH:	
CASING DIAMETER (IN.): 10	CASING LENGTH (FT.):	TYPE OF CASING: PVC
DEPTH TO STATIC WATER LEVEL: 36Ft.	DATE WELL COMPLETED:	
WHY IS THE WELL BEING ABANDONED? Replaced with GW-51146		

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)

Removed casing below ground level. Installed 5% chlorine bleach. Installed sand and gravel. Installed bentonite hole plug.

RECEIVED
MAY 12 2020
BY OLWR

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.

<u>Patrick M Chism</u>	<u>0695</u>
PRINT NAME	MS LICENSE NUMBER
<u>[Signature]</u>	<u>5-8-2020</u>
SIGNATURE	DATE



Google Earth



RECEIVED
MAY 12 2020
BY OLWR