

Abandonment Info for Yazoo wells per Billy Hill, DU

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
Office of Land and Water Resources
P. O. Box 2309
Jackson, MS 39225
Water Well Plugging/Decommissioning Form
OLWR-DF-1 (04/08)


COUNTY WELL LOCATED: Washington	WELL NUMBER: N
PERMIT NUMBER: GW-00252	DATE WELL PLUGGED: 8-27-2018
NAME OF FIRM PLUGGING WELL: Irrigation Equipment Inc.	TELEPHONE NUMBER: 662-887-2555
NAME AND ADDRESS OF CURRENT LANDOWNER: Yazoo NWR 595 Yazoo Refuge Rd Hollandale MS 38748	662-839-2638
WELL LOCATION: NE/NW SECTION: 27 TOWNSHIP: 15N RANGE: 8W	
WELL LOCATION: LATITUDE: 33 07 24.61 LONGITUDE: 91 00 40.10	METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) GPS - HAND HELD OR SURVEY GRADE
DISTANCE: DIRECTION: NEAREST TOWN: OTHER LANDMARK:	
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Wildlife Management	
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:	
NAME OF LANDOWNER WHEN WELL WAS DRILLED:	

no drill log

WELL DATA			
WELL DEPTH: 91ft	HOLE DEPTH:		
CASING DIAMETER (IN.): 16	CASING LENGTH (FT.):	TYPE OF CASING: PVC	
DEPTH TO STATIC WATER LEVEL: 22ft	DATE WELL COMPLETED:		
WHY IS THE WELL BEING ABANDONED?			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.)
Removed casing below ground level. Installed 5% chlorine bleach. Installed sand and gravel. Installed bentonite hole plug.

RECEIVED
OCT 03 2019
BY OLWR

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.	
Patrick M Chism	0695
	MS LICENSE NUMBER
PRINT NAME	11-5-2018
SIGNATURE	DATE