

MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY
Office of Land and Water Resources
 P. O. Box 2309
 Jackson, MS 39225
Water Well Plugging/Decommissioning Form
 OLWR-DF-1 (04/08)


no drill log

COUNTY WELL LOCATED: Washington		WELL NUMBER: N
PERMIT NUMBER: GW-00549	DATE WELL PLUGGED: 8-27-2018	
NAME OF FIRM PLUGGING WELL: Irrigation Equipment Inc.		TELEPHONE NUMBER: 662-887-2555
NAME AND ADDRESS OF CURRENT LANDOWNER: Yazoo NWR 595 Yazoo Refuge Rd Hollandale MS 38748		662-839-2638
WELL LOCATION: NW/NW	SECTION: 27	TOWNSHIP: 15N RANGE: 8W
WELL LOCATION: 33 07 28.59	LATITUDE: 33 07 28.59	LONGITUDE: 91 00 51.42 METHOD (CIRCLE ONE): (1) USGS QUAD (2) CONVENTIONAL SURVEY (3) GPS - HAND HELD OR SURVEY GRADE
DISTANCE:	DIRECTION:	NEAREST TOWN: OTHER LANDMARK:
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL, ETC.): Wildlife Management		
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL:		
NAME OF LANDOWNER WHEN WELL WAS DRILLED:		

WELL DATA			
WELL DEPTH: 89ft	HOLE DEPTH:		
CASING DIAMETER (IN.): 16	CASING LENGTH (FT.):	TYPE OF CASING: PVC	
DEPTH TO STATIC WATER LEVEL: 22ft	DATE WELL COMPLETED:		
WHY IS THE WELL BEING ABANDONED? Replaced			

DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE, MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.) Removed casing below ground level. Installed 5% chlorine bleach. Installed sand and gravel. Installed bentonite hole plug.
New Well: 33 07 27.7 91 00 51.8

RECEIVED
OCT 03 2019
BY OLWR

I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.	
Patrick M Chism	0695
	
PRINT NAME	MS LICENSE NUMBER
SIGNATURE	11-5-2018
	DATE



Google Earth



RECEIVED
OCT 03 2019
BY OLWR