

YALO.  
J 15

WATER WELL DRILLERS LOG

CODED  
CODED

Date: 12-10, 1961, Driller: T.B. CAIN County: PANOLA  
12-10-61 (Name)

(1) Owner of Land: CLOVIS HARBIN  
(Name)

SCOBY MISS  
(Address)

(2) Location: 32 24 4E  
32 24 4E T&R N  
12 miles north, of Shanda  
(distance) (direction) (Nearest Town)

(3) Topography: \_\_\_\_\_  
(Hilly) (Flat) (Level)

(4) Purpose of Well: Home  
(Domestic Irrigation  
Municipal, Industrial, Other)

Description & Color of Materials Sand, Clay, Red Clay, Shell, etc.	Thick- ness Feet	Depth Feet
<u>Clay</u>	<u>0</u>	<u>60</u>
<u>shale</u>	<u>60</u>	<u>85</u>
<u>Sand</u>	<u>85</u>	<u>105</u>

Information upon completion of well:

(1) Diameter 2 inches.

(2) Total Depth 105 feet.

(3) Water Level 63 feet below top of ground.

(4) Cased to 105, Size 2"


(5) Screen: Size 1/4, Length 6 FT

(6) Were any formations sealed against pollution?  
\_\_\_\_\_ yes,  no.

If YES depth of formation \_\_\_\_\_

Why \_\_\_\_\_

Drillers Remarks: non



(Use Back Side)

Well No.

