

YAZOO

D6

MISSISSIPPI BOARD OF WATER COMMISSIONERS

WATER WELL DRILLERS LOG

CODED

5-20-66

Date: 5-20, 1966, Driller: David Benny, County Yazoo

(When well drilled) 0418

(Name)

(Where well is located)


(1) Owner of Land: Mrs. Eunice Lemmon (Name)
At. 1 Pickens (Address)
(2) Location: 1/4, 1/4, Sec. 19 T12 R2E
(3) Topography: Hilly
(4) Purpose of Well: D

Table with 4 columns: Description & Color of Materials, Thickness Feet, Depth Feet. Rows include Clay, Clay with fine sand, Clay with sand, Sand with clay, etc.

Information upon completion of well:

(1) Diameter 2 inches.
(2) Total Depth 418 feet.
(3) Water Level feet below top of ground.
(4) Cased to 400, Size 2"
(5) Screen: Size 2", Length 10 ft.
(6) Were any formations sealed against pollution?

CODED



The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by a valid receipt or invoice. This ensures transparency and allows for easy verification of the data.

In the second section, the author outlines the various methods used to collect and analyze the data. This includes both manual and automated techniques. The goal is to ensure that the information gathered is both reliable and comprehensive.

The third part of the document provides a detailed breakdown of the results. It shows that there has been a significant increase in the number of transactions over the period studied. This growth is attributed to several factors, including improved marketing strategies and a more efficient distribution network.

Finally, the document concludes with a series of recommendations for future work. It suggests that further research should be conducted to explore the long-term effects of the current strategies. Additionally, it recommends that the organization continue to invest in technology to streamline its operations and improve its overall performance.