MISSISSIPPI DEPARTMENT OF ENVIRONMENTAL QUALITY

Office of Land and Water Resources

P. O. Box 2309

Jackson, MS 39225
Water Well Plugging/Decommissioning Form
OLWR-DF-1 (04/08) 1 1011 #7 (601)961-5555 (601)961-5228 (fax)

Well a	
COUNTY WELL LOCATED: Y4200	WELL NUMBER: 163 CCCSS
PERMIT NUMBER:	DATE WELL PLUGGED: 1-15-2019
NAME OF FIRM PLUGGING WELL: WEST WAR (WE !	TELEPHONE NUMBER: 601-428-1385
NAME AND ADDRESS OF CURRENT LANDOWNER:	
Denbury Resources 5320 Legacy Dr. PlanoTx 75024	
WELL LOCATION: SECTION: TOWNSHIP: RANGE:	
well location: Latitude: Longitude: 32.746042 ~90.4630 71	METHOD (Check ONE): USGS QUAD □) CONVENTIONAL SURVEY 3) GPS — HAND HELD OR SURVEY GRADE
DISTANCE: 7 m; DIRECTION: S NEAREST TOWN: YOZOOCITY OTHER LANDMARK:	
WELL PURPOSE (HOME, IRRIGATION, MUNICIPAL ETC.):	
NAME OF WELL CONTRACTOR WHO DRILLED THE WELL: Westwate (1 well	
NAME OF LANDOWNER WHEN WELL WAS DRILLED: DENDULY RESOURCE	
WELL DATA	
WELL DEPTH: 390	HOLE DEPTH: 390
CASING DIAMETER (IN.): 4 CASING LENGTH (FT.): 33	D TYPE OF CASING: PV C
DEPTH TO STATIC WATER LEVEL: 108' DATE WELL COMPLETED: 11-9-2018	
WHY IS THE WELL BEING ABANDONED? No longer needed	
DESCRIBE HOW THE WELL OR HOLE WAS PLUGGED (AMOUNT OF CASING AND/OR SCREEN THAT WAS REMOVED OR LEFT IN HOLE,	
MATERIAL AND AMOUNT USED IN PLUGGING, METHOD OF PLACING MATERIAL, ETC.) Screens were Derforated wait operated perforator. 330-390	
Bentonike chipswere powed through 2" tremie pipe, tamping intermittently	
when chips were in sight, last joint of tremie was removed	
Casina was cut off 5th below surface	
Concrete was used to Finish Filling hole + 14-18: n above (asing cut off	
	4.4
I CERTIFY THAT THE WELL WAS PLUGGED OR ABANDONED IN ACCORDANCE WITH THE STATE OF MISSISSIPPI REGULATIONS.	
Day of Wost	©-61A
1 2 1 PRAIT HAMP	MS LICENSE NUMBER
Lux Us	<u>3-17-901d</u>
SIGNATURE	DATE