

UNITED STATES

DEPARTMENT OF THE INTERIOR
BUREAU OF GEOLOGICAL SURVEY
WATER RESOURCES DIVISION

WELL SCHEDULE

Date _____

Record by _____

Source of data _____

1. Location _____

Map _____

2. Owner _____

Address _____

Address _____

Address _____

3. Township _____

4. Elevation _____

5. Type: Dug/Drilled _____

6. Dept. Rept. No. _____

7. Containing: Dam _____

8. Chief Engineer _____

9. Others _____

10. Water level _____

11. Yield _____

12. Draw down _____

13. Use: (Dom. Stock, Irr., Ind., etc.) _____

14. Remarks: (Log, etc.) _____

Well 099 drilled to 1000' at 8000' + blasted and rebuilt. Air lift re-arranged in 1934 to 400' depth. 389' cleaned in 1934. perf. about 395-400'.

Water shortage at 8000' + blasted and rebuilt. Air lift re-arranged in 1934 to 400' depth. 389' cleaned in 1934. perf. about 395-400'.

700' 8" and 300' of 10" casing plugged all thru 87' below 400' casing.

8-1-57
Ch. Eng. GAYTOR Mobil, AL

15. Notes: (Log, etc.) _____

16. _____

17. _____

18. _____

19. _____

20. _____

21. _____

22. _____

23. _____

24. _____

25. _____

26. _____

27. _____

28. _____

29. _____

30. _____

31. _____

32. _____

33. _____

34. _____

35. _____

36. _____

37. _____

38. _____

39. _____

40. _____

41. _____

42. _____

43. _____

44. _____

45. _____

46. _____

47. _____

48. _____

49. _____

50. _____

51. _____

52. _____

53. _____

54. _____

55. _____

56. _____

57. _____

58. _____

59. _____

60. _____

61. _____

62. _____

63. _____

64. _____

65. _____

66. _____

67. _____

68. _____

69. _____

70. _____

71. _____

72. _____

73. _____

74. _____

75. _____

76. _____

77. _____

78. _____

79. _____

80. _____

81. _____

82. _____

83. _____

84. _____

85. _____

86. _____

87. _____

88. _____

89. _____

90. _____

91. _____

92. _____

93. _____

94. _____

95. _____

96. _____

97. _____

98. _____

99. _____

100. _____

