

Note: all w.r. are in as A35 → used Lake Cormorant Quad  
3/81 wrong well # since 1980 A # 1

6/78 WFO

TRANSMITTED FOR ADP

U.S. GEOLOGICAL SURVEY  
WATER RESOURCES DIVISION  
MISSISSIPPI DISTRICT  
WELL RECORD

Well No. A55  
E-Log No. \_\_\_\_\_  
County Desoto

Recorded by BSCW  
Date 8/19/80

Site ID 345712.090.0945.01 R=0\* T=A\* 2=W\*

Data reliab. 3=C\* Report. agency 4=USGS\* Dist. 6=28\* 7=28\* Co. 8=033\*

Lat. \_\_\_\_\_ Long. 9=345712\* 10=0900945\* Well No. 12=A055\*

Location 13=NW1/4S33T01SR09W\* Alt. 16=213\*

Hyd. Unit (OWDC) 20= Date 21=0911911980\*

Well use 23=W\* Water Use 24=H\* Hole depth 27= Well depth 28=32\*

30=14\* Date 31=0911911980\* Source 33=S\*

Status 273= Project No. 5=

R=158\* T=A\* Date 159#0911911980\* Owner No. \_\_\_\_\_

Owner 161#TURNER FLOWERS\*

R=192\* T=A\* Date 193# Temp. 196#00010\* 197=

R=192\* T=A\* Date 193# Cond. 196#00095\* 197=

R=192\* T=A\* Date 193# pH 196#00400\* 197=

R=58\* T=A\* 59#1\* Date 60=0110111980\* Remarks \_\_\_\_\_

Drlg. 63= Name \_\_\_\_\_ Method 65=H\* Finish 66=

R=76\* T=A\* 59#1\*  
Top csng. 77#0\* Bot. csng. 78= Diam. 79#1\*

R=76\* T=A\* 59#1\*  
Top csng. 77# Bot. csng. 78= Diam. 79#

R=82\* T=A\* 59#1\* Top 83# Bottom 84=

Type 85= Diam. 87= Size 88=

R=82\* T=A\* 59#1\* Top 83# Bottom 84=

Type 85= Diam. 87= Size 88=

R= T=A\* 147#1\* Q 150= Q/S 272=

134 flows 146 pumped

R=42\* T= A \* Lift type 43# \* Intake 44= \* Power type 45= \*

LIFT

Date 38= / / \* H.P. 46= \* \*

R=198\* T= A \* Log 199# \* Top 200= \* Bot 201= \*

LOGS

R=198\* T= A \* Log 199# \* Top 200= \* Bot 201= \*

R=189\* T= A \* E Log No. 190# \* 191= M I S S D I S T \*

ANAL.

R=114\* T= A \* Year 115# \* Type 120= \*

AQUIFERS

R=90\* T= A \* 256# 1 \* Top 91= \* Bot 92= \*

Unit ID 93= 1.12 MRVA \* Name of Unit MISS RIVER VALLEY ALLUV.

R=90\* T= A \* 256# 1 \* Top 91= \* Bot 92= \*

Unit ID 93= \* Name of Unit

HYDRAULICS

R=98\* T= A \* 99# 1 \* Unit tested 100= \* 103= \*

R=105\* T= A \* 99# 1 \* Test No. 106# \*


107= \* Transmissivity (gal/d)/ft

108= \* Hydraul. cond. (gal/d)/ft<sup>2</sup>

110= \* Storage coeff. Boundaries

R=121\* T= A \* Yr. Begin 122# 1980 \* Network 258= \*

Water Level Data Collection (1)



LIFT

R=42\* T= A \* Lift type 430 \* Intake 44= \* Power type 45= \*

Date 38= / / H.P. 46= \*

LOGS

R=198\* T= A \* Log 199# \* Top 200= \* Bot 201= \*

R=198\* T= A \* Log 199# \* Top 200= \* Bot 201= \*

R=189\* T= A \* E Log No. 190# \* 191= M I S S D I S T \*

ANAL.

R=114\* T= A \* Year 115# \* Type 120= \*

AQUIFERS

R=90\* T= A \* 256# 1 \* Top 91= \* Bot 92= \*

Unit ID 93= 112 M R V A \* Name of Unit MISS RIVER VALLEY ALLUV.

R=90\* T= A \* 256# 1 \* Top 91= \* Bot 92= \*

Unit ID 93= \* Name of Unit

HYDRAULICS

R=98\* T= A \* 99# 1 \* Unit tested 100= \* 103= \*

R=105\* T= A \* 99# 1 \* Test No. 106# \*


107= \* Transmissivity (gal/d)/ft

108= \* Hydraul. cond. (gal/d)/ft<sup>2</sup>

110= \* Storage coeff. Boundaries

R=121\* T= A \* Yr Begin 122# 1980 \* Network 258= \*

Water Level Data Collection (1)





# LAKE CORMORANT QUAD

