

Coded By Q 894
 Checked By Q 894
 Entered By Q 894
 Date 2/9/94

U.S. GEOLOGICAL SURVEY
 WATER RESOURCES DIVISION
 MISSISSIPPI DISTRICT

E-Log No. 396A
 County JACKSON
 Agency

Well No. M 322
396A

WELL RECORD

Agency Code <u>U1SIGIS</u>	Site Id <u>11310218151018182141516011</u>	Project No. <u>54059</u>
Station Name <u>12 M322 MARY KALUAHAIN</u>	Latitude <u>9 30 21 85 ST</u>	Longitude <u>10 01 81 24 56 I</u>
Lac/Long Ac. <u>11 S F M</u>	Dist <u>6=29</u>	State <u>7=28</u>
County <u>8=059</u>	Land Net <u>13 SIENETS3111016SR104W</u>	
Location Map <u>14 IKREIOLKE</u>	Altitude <u>16 115</u>	Mec/Meas <u>17 A L M</u>
Accuracy <u>18 1 15</u>	Hydrologic Unit <u>20 01311709081</u>	
Agency Use <u>803 A I O</u>	Date Inventoried <u>7 11 / /</u>	Station Type <u>4 Y</u>
Data Type <u>804</u>		
Instru. <u>905</u>	Remarks <u>806</u>	Relia. <u>3 C M U</u>
Date of Construction <u>21 05 / 07 / 11 1984</u>	Well Use <u>23 W</u>	Water Use <u>24 H</u>
Primary Aquifer <u>714 216 R M A</u>	Hole Depth <u>27 1394</u>	
Well Depth <u>28 1390</u>	Water Level <u>30</u>	Water Level Date <u>31 05 / 07 / 11 1984</u>
Method <u>34</u>	Status <u>37 F</u>	Source <u>33 D</u>

CONSTRUCTION DATA

Construction Date <u>60 05 / 07 / 11 1984</u>	Contractor <u>63 158</u>	Name <u>COAST</u>	Method <u>65 H</u>	Finish <u>66 S</u>
--------------------------------------------------	-----------------------------	----------------------	-----------------------	-----------------------

CONSTRUCTION CASING DATA

Top/Casing <u>R=76</u>	Bot/Casing <u>T=A</u>	Diameter <u>725#1</u>	Top/Casing <u>59#1</u>	Bot/Casing <u>77</u>	Diameter <u>77 101</u>	Top/Casing <u>78</u>	Bot/Casing <u>37101</u>	Diameter <u>79 14</u>
Top/Casing <u>R=76</u>	Bot/Casing <u>T=A</u>	Diameter <u>725#2</u>	Top/Casing <u>59#1</u>	Bot/Casing <u>77</u>	Diameter <u>77</u>	Top/Casing <u>78</u>	Bot/Casing <u></u>	Diameter <u>79</u>

CONSTRUCTION OPENINGS DATA

Top/Depth <u>R=82</u>	Bot/Depth <u>T=A</u>	Diameter <u>726#1</u>	Top/Depth <u>59#1</u>	Bot/Depth <u>83 37101</u>	Diameter <u>84 37101</u>	Top/Depth <u>87 4</u>	Bot/Depth <u>85 S</u>	Diameter <u>89</u>	Length <u>88</u>	Width <u></u>
Top/Depth <u>R=82</u>	Bot/Depth <u>T=A</u>	Diameter <u>726#2</u>	Top/Depth <u>59#1</u>	Bot/Depth <u>83</u>	Diameter <u>84</u>	Top/Depth <u>87</u>	Bot/Depth <u>85</u>	Diameter <u>89</u>	Length <u>88</u>	Width <u></u>

CONSTRUCTION LIFT DATA

Lift Type <u>R=42</u>	H.P. <u>T=A</u>	Serial No. <u>254#1</u>	Date <u>43</u>	Intake <u>38</u>	<u>44</u>
<u>45</u>	<u>46</u>	<u>49</u>			

MISCELLANEOUS OWNER DATA

Date of Ownership <u>R=158</u>	Owner Name <u>T=A</u>	<u>718#1</u>	<u>159 05 / 07 / 11 1984</u>	<u>161 MARY KALUAHAIN</u>
-----------------------------------	--------------------------	--------------	------------------------------	---------------------------

MISCELLANEOUS OTHER ID DATA

E-Log No.	Assigner
<u>100 1 1 1</u>	<u>101 J M R C S I N I R I S T I</u>

