



LIFT

R=42\* T= A \* Lift type 43# S\* Intake 44= \* Power type 45= D\*  
 Date 38= 05/10/1985\* H.P. 46= 80.\*

LOGS

R=198\* T= A \* Log 199# D\* Top 200= 0.\* Bot 201= 9.5.\*  
 R=198\* T= A \* Log 199# \* Top 200= \* Bot 201= \*  
 R=189\* T= A \* E Log No. 190# \* 191= M I S S D I S T \*

ANAL.

R=114\* T= A \* Year 115# \* 117= \* 120= \*

AQUIFERS

R=90\* T= A \* 256# 1 \* Top 91= 25.\* Bot 92= 9.4.\*  
 Unit ID 93= 112MRVA \* Name of Unit \_\_\_\_\_  
 R=90\* T= A \* 256# 1 \* Top 91= \* Bot 92= \*  
 Unit ID 93= \* Name of Unit \_\_\_\_\_

HYDRAULICS

R=98\* T= A \* 99# 1 \* Unit tested 100= \* 103= \*  
 R=105\* T= A \* 99# 1 \* Test No. 106# \*  
 107= \* Transmissivity (gal/d)/ft \_\_\_\_\_  
 108= \* Hydraul. cond. (gal/d)/ft<sup>2</sup> \_\_\_\_\_  
 110= \* Storage coeff. Boundaries \_\_\_\_\_

R=121\* T= \* Yr Begin 122# \* Network 258# \*

Water Level Data Collection (1)

6 miles NW of Ittabena

description of formations encountered	from	to
Clay	0	25
fine sand	25	55
sand gravel	55	94
rock	94	95