

9-185 July, 1918

DEPARTMENT OF THE INTERIOR
UNITED STATES GEOLOGICAL SURVEY
WATER RESOURCES BRANCH

Center
carded
+

Well Schedule

Date

Sept 38 19 19

Field No.

CHK 106

Record by

Ch Kidwell

Office No.

018

1. Location: State Missouri County Monroe

Quarter 2 Secs 5 W of MTA depot
NW SE 1/4 sec 34 T 15 N R 6 P W

2. Owner J.C. Cunningham Address Mildon

Driller Robert Utterback Address California

3. Topography level prairie country

4. Altitude 2 ft. above MTA RR

5. Type Dug, drilled, driven, bored

6. Depth 360 ft. Date about 1898

7. Diameter: top 2 ft. bottom 2 ft.

8. Chief Aquifer entire sands

9. Casing: Type iron pipe Depth 110 ft. Diam 2 ft. to

Finish no strain

10. Water level 80 ft. above surface

11. Pump: Type hand Capacity _____ G. M.

Power: Kind _____ Horsepower _____

12. Yield: Flow no flow G. M. Pump _____ G. M. Meas. Rept _____

Drawdown _____ ft.; pumping _____ G. M.; time _____

13. Use: Dom., Stock, PG, RR, Ind., DW, Irr. _____ Quantity _____

Adequacy, permanence both

14. Quality: Good, fair, bad _____ Sample Yes _____ No _____

Taste, odor, color _____ Temp _____ °F

Unfit for _____

Sanitation _____

15. Cost: Well, \$ _____; Plant (well, pump, power, etc.), \$ _____

Operating, \$ _____ per _____ inc. _____ exc. Parties

Log, analysis, authority J.C. Cunningham on back page

This is case below description which occurs at 20 ft.

