



LIFT

R=42\* T= A \* Lift type 43# A\* Intake 44= \* Power type 45= \*

Date 38= 05/17/1980\* H.P. 46= \*

LOGS

R=198\* T= A \* Log 199# D\* Top 200= 0\* Bot 201= 399\*  
 R=198\* T= A \* Log 199# \* Top 200= \* Bot 201= \*  
 R=189\* T= A \* E Log No. 190# \* 191= M I S S D I S T \*

ANAL.

R=114\* T= A \* Year 115# \* Type 120= \*

AQUIFERS

R=90\* T= A \* 256# 1 \* Top 91= 105\* Bot 92= 357\*  
 Unit ID 93= 122MDCN\* Name of Unit MIOCENE  
 R=90\* T= A \* 256# -1 \* Top 91= \* Bot 92= \*  
 Unit ID 93= \* Name of Unit \*

HYDRAULICS

R=98\* T= A \* 99# 1 \* Unit tested 100= \* 103= \*  
 R=105\* T= A \* 99# 1 \* Test No. 106# \*  
 107= \* Transmissivity (gal/d)/ft  
 108= \* Hydraul. cond. (gal/d)/ft<sup>2</sup>  
 110= \* Storage coeff. Boundaries

R=121\* T= \* Yr Begin 122# \* Network 258= \*

Water Level Data Collection (1),  
1500' N 8 1/50' W of SE/COR

description of formations encountered	from	to
<u>clay</u>	<u>0</u>	<u>105</u>
<u>sand-gravel</u>	<u>105</u>	<u>357</u>
<u>clay</u>	<u>357</u>	<u>399</u>

2043