

MS DAMS

Inspection Report

StateID:

MS02616

Dam Name:

MEMORIAL PARK CEMETERY POND DAM

Hazard Class:

H

County:

LAUDERDALE

Inspection Type:

STATE

Inspection Date:

2/15/2017

Inspectors:

A. CUMMINGS

Primary Spillway Type:

CULVERT

Primary Spillway Size:

24 INCH RCP

Primary Spillway Condition:

GOOD CONDITION.

Emergency Spillway Type:

EARTHEN

Emergency Spillway Size:

N/A

Emergency Spillway Condition:

GOOD.

Upstream Slope:

FAIR - SOME AREAS OF MINOR EROSION.

Downstream Slope:

FAIR CONDITION - ANIMAL BURROW OR SMALL SINKHOLE OBSERVED AT DOWNSTREAM TOE OF DAM.

Top of Dam:

GOOD CONDITION. PAVED. 20 FEET WIDE.

Seepage:

NONE OBSERVED

Outlet Channel:

GOOD CONDITION. CHANNEL APPEARS TO BE DEEPENING OVER TIME.

Pictures Taken?:

Y

Suggested Repairs/Improvements:

ADD SLOPE PROTECTION TO THE UPSTREAM SLOPE; REMOVE BURROWING ANIMALS FROM DAM, AND MONITOR POTENTIAL SINKHOLE AND OUTLET CHANNEL SIDES FOR ANY CHANGES.

Recommendations:

Comments:

Description of Downstream Hazard:

HOUSES.

Inspection Status: FAIR

Remediation Needed?: Y

Enforcement Needed?: N

