

MS DAMS Inspection Report



StateID:

MS03260

Dam Name:

TOWN CREEK WS STR 14 DAM

Hazard Class:

H

County:

PONTOTOC

Inspection Type:

STATE

Inspection Date:

6/22/2021

Inspectors:

J PARRISH AND A TUTOR

Primary Spillway Type:

RISER AND CONDUIT

Primary Spillway Size:

7.5 FT BY 2.5 FT RISER BY 30 IN CONDUIT

Primary Spillway Condition:

GOOD CONDITION

Emergency Spillway Type:

TWO-BOTH EARTHEN VEGETATED

Emergency Spillway Size:

200' BW AND A 150 FT BW

Emergency Spillway Condition:

REMOVE TREES AND BRUSH FROM SPILLWAYS.

Upstream Slope:

GOOD.

Downstream Slope:

GOOD.

Top of Dam:

RUTS, SOME UP TO 6" DEEP, EXTEND OVER A LARGE PORTION OF THE CREST.

Seepage:

NONE NOTED

Outlet Channel:

COULD NOT ASSESS DUE TO OVERGROWN VEGETATION.

Pictures Taken?:

Y

Suggested Repairs/Improvements:

REPAIR RUTS THAT EXTEND FOR MOST OF THE CREST LENGTH. REMOVE TREES AND BRUSH FROM SPILLWAYS. RETURN TO CHECK OUTLET STRUCTURES AFTER VEGETATION IS CLEARED.

Recommendations:

Comments:

Description of Downstream Hazard:

COMMERCIAL

Inspection Status: FAIR

Remediation Needed?: Y

Enforcement Needed?: N

