

MS DAMS Inspection Report



StateID:

MS03288

Dam Name:

TOWN CREEK WS STR 13 DAM

Hazard Class:

H

County:

PONTOTOC

Inspection Type:

STATE

Inspection Date:

6/22/2021

Inspectors:

J PARRISH AND A TUTOR

Primary Spillway Type:

RISER AND CONDUIT

Primary Spillway Size:

Primary Spillway Condition:

DOOR/ACCESS DAMAGED FROM RECENT HEAVY RAIN EVENTS.

Emergency Spillway Type:

TWO- EARTHEN VEGETATED

Emergency Spillway Size:

ONE 240' THE OTHER 480'

Emergency Spillway Condition:

TREES AND BRUSH PRESENT WITHIN BOTH SPILLWAYS.

Upstream Slope:

GOOD

Downstream Slope:

TREES, BRUSH, AND DEER STANDS/STRUCTURES ARE PRESENT WITHIN 50' OF THE TOE.

Top of Dam:

GOOD

Seepage:

NONE NOTED.

Outlet Channel:

GOOD

Pictures Taken?:

Y

Suggested Repairs/Improvements:

REPAIR ACCESS DOOR ON PRIMARY SPILLWAY. REMOVE TREES, BRUSH, AND STRUCTURES FROM WITHIN 50' OF THE TOE AND FROM BOTH AUXILIARY SPILLWAYS.

Recommendations:

Comments:

Description of Downstream Hazard:

Inspection Status: SATISFACTORY

Remediation Needed?: Y

Enforcement Needed?: N

